



EXPOSED SURFACE



No.1

EXPOSED SURFACE



No.2

NOTE :

1. BREAK ALL SHARP EDGES
2. POLISH ON EXPOSED SURFACE