

OSCULATI Group



Boating simply

TEST NEBBIA SALINA DEL 08/04/2019

Salt spray chamber test 08/04/2019



Articolo
Article
13.448.00



APERTURA MACCHINA PER INSERIMENTO ARTICOLI

Machine opening to put inside the items



NEBBIA SALINA IN FUNZIONE

Working Salt Spray



ARTICOLO A FINE TEST

The article at the end of the test



ARTICOLO A FINE TEST

The article at the end of the test



ARTICOLO A FINE TEST

The article at the end of the test



ESITI DEL TEST

Test results



- Metodo standard ASTM 117 – Standard way ASTM 117
- Durata test 72 h – Test time 72 h
- **Nessun segno** di presenza di ruggine – **No sign** of the presence of rust

Mauro Di Giorgio
Customer Technical Support